



FFL 90.600

- Revisions**
- F Information Issue 03.06.05
  - F Status change to T1. Issued for Information 10.06.05
  - G Staircase Phase 1. Status change to CD. 07.10.05
  - H Phase 2A added. University room numbers added. 11.11.05
  - I Atrium & circular stairs updated. Corridor width amended. Seismic lifts updated. Mini Forum walls amended.
  - J Lift shafts + car updated. 17.03.06
  - J Specialist Joinery design development 14.07.06
  - K Steel updated to match BH drawings. Pantries and coffee points updated. Status change to CA. 11.08.06
  - L Window at gridlines K & 25 corrected 06.10.06
  - M Printing areas updated 18.10.06
  - N Core D windows adjusted. 23.10.06
  - O Printing area wall moved. M&E risers added. Lockers shown. Structure checked. Stair SP04 updated. 29.11.06
  - P Door positions checked. 05.12.06
  - Q 06.05.07 C&P Changes. Timber panelling omitted. Return air path omitted. Door dimensions adjusted. Window to printing area omitted.
- Notes**

**Roofing Notes**

---	Direction of fall of roof membrane
RWO	Rainwater outlet
RWP	Rainwater downpipe
OF	Rainwater overflow
SVP	Soil vent pipe

**Bennetts Associates  
Architects**

- 3 Boroughloch Square Edinburgh EH8 9NJ
- Tel: +44 (0)131 667 7351
- Fax: +44 (0)131 662 1867
- E-mail: potterrow@bennettsassociates.com

Project  
**Potterrow Development  
for University of Edinburgh**

Drawing Title <b>Phase 1 Second Floor Plan</b>	job no. <b>0312</b>	drawing no. <b>A(E)-102</b>	rev <b>Q</b>	status <b>CA</b>
	scale @ A3 <b>1:200</b>	scale @ A1 <b>1:100</b>	date <b>Oct 2004</b>	